


TO 02 90° TE 6338610

Sheet 1 of 12

Image-00752.11. frame-00:085223, radar frame-857



BEST AVAILABLE COPY

FIG. 1

Sheet 2 of 12




FIG. 2

FIGURE 30 "TEC938860

Sheet 3 of 12




FIG. 3

70290*TE698860

Sheet 4 of 12




FIG. 4

FIGURE 500 "TELEGRAM

Sheet 5 of 12




FIG. 5

Sheet 6 of 12




FIG. 6

Sheet 7 of 12




FIG. 7

Sheet 8 of 12

Horizontal edge histogram profiles without vertical vibration compensation




Image frames

FIG. 8a

தொடர்பு - தெர்க்கப்படுத்த

Sheet 9 of 12

Horizontal_edge_histogram profiles after vertical vibration compensation




Image frames

FIG. 8b

Sheet 10 of 12




FIG. 8c

FIG. 2 Sheet 1 of 12




FIG. 9

TO TO 30° T E 6 9 8 8 6 0

Sheet 12 of 12




FIG. 10

**This Page is Inserted by IFW Indexing and Scanning
Operations and is not part of the Official Record**

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- BLACK BORDERS**
- IMAGE CUT OFF AT TOP, BOTTOM OR SIDES**
- FADED TEXT OR DRAWING**
- BLURRED OR ILLEGIBLE TEXT OR DRAWING**
- SKEWED/SLANTED IMAGES**
- COLOR OR BLACK AND WHITE PHOTOGRAPHS**
- GRAY SCALE DOCUMENTS**
- LINES OR MARKS ON ORIGINAL DOCUMENT**
- REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY**
- OTHER:** _____

IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.